



January 27, 2006

Ms. Joan Fleck
Regional Water Quality Control Board
North Coast Region
5550 Skylane Boulevard, Suite A
Santa Rosa, California 95403

00307

06.a3

**Re: Quarterly Status Report
Former ARCO Service Station No. 307
210 Fifth Street
Santa Rosa, Sonoma County, California**

Dear Ms. Fleck:

URS Corporation Americas (URS) is submitting this quarterly status report for the Atlantic Richfield Company (ARCO – a BP affiliated company) former Service Station No. 307, located at 210 Fifth Street, Santa Rosa, California. During fourth quarter, URS generated a well abandonment summary report dated November 16, 2005 documenting the destruction of groundwater monitoring wells MW-1, MW-2, and MW-3.

If you have any questions regarding this report, please call Scott Dressler at (530) 893-9675.

Sincerely,

URS Corporation Americas

Amanda Atkinson
Staff Geologist

D. Scott Dressler, P.G.
Project Manager

cc: Mr. Chuck Carmel, Atlantic Richfield Company (via ENFOS)

URS Corporation
1550 Humboldt Road, Suite 2
Chico, CA 95928
Tel: 530.893.9675
Fax: 530.893.9682

\\Chicodata2\\env\\Projects\\BP - Arco\\Project Sites\\NON-QTRLY SITES\\00307\\Project Files\\QSR\\307 QSR COVER.doc